

25X1A ~~SECRET~~ NO [REDACTED] Approved For Release 2000/06/14 : CIA-RDP78-06505A000700060004-0
DATE - 11 FEBRUARY 1969

TO - CHIEF, FAR EAST DIVISION
INFO - DIRECTOR OF LOGISTICS
FROM - CHIEF OF STATION, [REDACTED]
SUBJECT - ADMIN/PERS/LOGS/[REDACTED]
ACTION - SEE PARA 1

25X1A

REFERENCE - DIRECTOR 71522 *Re P-11*

25X1A 1. [REDACTED] WHO IS FAMILIAR WITH [REDACTED] HAS

25X1A

25X1A BRIEFED [REDACTED] ON THE GENERAL DUTIES OF THIS ASSIGNMENT AS
HE REMEMBERS THEM. [REDACTED] IS INTERESTED IN THIS ASSIGNMENT,
HOWEVER HIS PERSONAL PREFERENCE WOULD BE TO DELAY HIS FINAL
DECISION UNTIL HE RETURNS TO HEADQUARTERS THIS SUMMER, HOWEVER,
HE REALIZES THAT THIS WOULD BE MUCH TOO FAR DOWN STREAM, SHOULD
HE DECIDE NOT TO ACCEPT THE ASSIGNMENT FOR YOU TO LOCATE A
REPLACEMENT. THEREFORE HE IS MOST ANXIOUS TO RECEIVE A DETAILED
BREAKDOWN OF THE SPECIFIC DUTIES, GRADE OF POSITION, STAFF
POSSIBILITIES, HOUSING, AND ANY OTHER INFORMATION AVAILABLE
WHICH WOULD ALLOW HIM AN OPPORTUNITY TO REVIEW THIS ASSIGNMENT
AND ADVISE YOU OF HIS DECISION ASAP.

25X1A

2. PER YOUR REQUEST IN PARA 2 OF REF THE LOCAL TELEPHONE

25X1A EXCHANGE IS STRONGER STEP-BY-STEP SWITCHING SYSTEM. THE

[REDACTED] EQUIPMENT IS IDENTICAL TO THAT MANUFACTURED BY
AUTOMATIC ELECTRIC CO. IT IS RECOMMENDED THAT TECHNICAL
BULLETIN 945-800 THROUGH 945-821 BE OBTAINED FROM THE AUTOMATIC
ELECTRIC CO. THE BULLETINS ARE SUPERIOR TO THAT SUPPLIED WITH THIS
SYSTEM BY THE [REDACTED] MANUFACTURER.

REC'D
30
200
1 EX 11-2-12
AC
SA
C/RE
O
C/ENG
DE
APPROVAL
COMMENT
CONCURRE
INFORMATIO
PREPARE REPLY
RETURN
FILE

6

25X1A

SECRET TELEPOUCH [REDACTED] PAGE ONE OF THREE ENDS

25X1A

3. DUE TO THE EXTENT OF THE 1A1 AND 1A2 KEY TELEPHONE
SYSTEM AND NOT RECESSARY
Approved For Release 2000/06/14 : CIA-RDP78-06505A000700060004-0

REPLACEMENT MUST HAVE BACKGROUND EXPERIENCE IN INSTALLATION
AND MAINTENANCE OF THIS EQUIPMENT. TECHNICAL DATA IS AVAIL-
ABLE FROM WESTERN ELECTRIC AND STROMBERG CARLSON.

4. THE CANDIDATE FOR THE ABOVE POSITION MUST HAVE MORE
THAN KNOWLEDGE OR THEORY ON TELEPHONE SYSTEM. HE MUST HAVE THE
CAPABILITY OF INSTALLING AND MAINTAINING CENTRAL OFFICE
AUTOMATIC DIAL SYSTEM EQUIPMENT IN ACCORDANCE WITH MANUFACTURER'S
INSTALLATION AND MAINTENANCE MANUALS. HE WILL BE REQUIRED TO
PERFORM AND/OR SUPERVISE THE FOLLOWING WORK--

- A. MAKE TESTS TO ANALYZE AND LOCATE TROUBLE-
- B. ADJUST OR REPLACE FAULTY ELEMENTS-
- C. REPAIR OR REPLACE CONTACTS ON SWITCHES, RELAYS, ETC.,-
- D. REPLACE FUSES, INDICATING LIGHTS, RELAYS, AND
CAPACITORS--
- E. REPLACE BURNED-OUT RECTIFIER ELEMENTS IN BATTERY
CHARGER-
- F. TERMINATE OUTSIDE CABLE AT TERMINAL BLOCK, RUNS ALL
INSIDE STATION LINES, AND CONNECT THEM TO SWITCHBOARD
TERMINAL-
- G. CONNECT AUXILIARY CIRCUITS-
- H. CAPABLE OF READING BLUEPRINTS, CIRCUIT DIAGRAMS,
AND ANALYZING VARIOUS TYPES OF CIRCUITS AND THEIR FUNCTIONS-
AND
- I. ASSIST OTHER FE STATIONS WHEN REQUESTED BY COS WITH
SECURE TELEPHONE AND ELECTRICAL INSTALLATIONS AND REPAIRS.

25X1A 5. [REDACTED] REPLACEMENT SHOULD ALSO HAVE HAD EXPERIENCE
WITH HIGH VOLTAGE ELECTRICAL POWER GENERATING, DISTRIBUTION
EQUIPMENT, AND ASSOCIATED EQUIPMENT, SUCH AS SWITCH GEAR, ETC.

SECRET TELEPOUCH [REDACTED] PAGE THREE

25X1A

THE ABOVE IS NOT MANDATORY BUT REQUESTED. ~~Approved For Release 2000/06/14 : CIA-RDP78-06505A000700060004-0~~

IS TO SUPERVISE THE SHOPS INVOLVED IN THE ABOVE WORK AND
THEREBY NOT PLACING ADDITIONAL BURDEN ON THE POST ENGINEER.

6. THE TECHNICAL LITERATURE FOLDERS, ONE THRU SEVEN,
ARE BEING FORWARDED UNDER SEPARATE COVER AND THEY MUST BE
RETURNED AFTER THE STUDY OR REVIEW HAS BEEN COMPLETED FOR OUR
FILES.

[REDACTED] 25X1A

END

ATTACHMENTS/VIA POUCH U/S/C

TECHNICAL LITERATURE FOLDERS, ONE THRU SEVEN

DISTRIBUTION/VIA TELEPOUCH

2 - CHIEF, FE DIVISION/VIA TP W/ATT U/S/C VIA POUCH

- DIRECTOR OF LOGISTICS/VIA TP W/O ATIS

SECRET TELEPOUCH [REDACTED] PAGE THREE OF THREE ENDS

25X1A

BT